

AR-509676

1a	8	Flam/Comb Paint Sludge
1b	65	Kolene
1c	79	Dry Toner
1d	12	Aerosol Cans
2a	81	Kerosene
2b	87	Stoddard Solvent
2c	8	Flam/Comb Paint Sludge



STATE OF ARKANSAS
Department of Pollution Control and Ecology
P. O. Box 8913 Little Rock, Arkansas 72219-8913
Telephone 501-562-7444

1

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-91

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A D D B 6 5 1 D D D 5 9 1 D B D		Manifest Document No. of 2		2. Page 1 Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address Douglas Aircraft Company Attn: R. Tuell M/S C6-59 19503 S. Normandie Avenue, Torrance, CA 90502				A. State Manifest Document Number AR- 509676			
4. Generator's Phone (213) 533-7926 or 213-533-7231				B. State Generator's ID HAH036005698			
5. Transporter 1 Company Name United Pumping Services				C. State Transporter's ID PC 1123 602-			
7. Transporter 2 Company Name				D. Transporter's Phone 818-961-9326			
9. Designated Facility Name and Site Address EnSCO, Inc. American Oil Road El Dorado, AR 71730				E. State Transporter's ID PC - - - - H - - -			
10. US EPA ID Number I A I R I D I Q I 6 I 9 I 7 I 4 I 8 I 1 I 9 I 2				F. Transporter's Phone 501-863-7173			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers		13. Total Quantity		14. Unit Wt/Vol	
		No. Type				L. Waste No.	
a. RQ, Waste, Paint Related Material Flammable Liquid, NA1263 (F002,F003,F005)		040 DM		200000		P F002,F003,F005 U080,U226,U289 U220,U161	
b. RQ, Waste, Oxidizer, Corrosive Solid, N.O.S. Oxidizer, NA9194 (D001,D002)(Potassium Nitrate)		078 D F		078000		P D001,D002	
c. RQ, Waste, Flammable Solid, N.O.S. (Dry Toner) Flammable Solid, UN1325 (D001)		001 D M		001000		P D001	
d. RQ, Waste, Compressed Gas, N.O.S. (Petroleum Distillates) Flammable Gas, UN1954 (D001)		004 D F		008000		P D001,U159 U220,U239	
J. Additional Descriptions for Materials Listed Above a) WMDS # 146135. Paint sludge. A 17583 # b) WMDS # 146142. Ketene. B 8818 # c) WMDS # 142768. Dry toner. C 94 # If no alternate TSD, return to generator D 655 #				K. Handling Codes for Wastes Listed Above EMERGENCY RESPONSE INFORMATION: 213-533-7926 Rob Tuell 213-830-1781 Tracy Takahashi			
15. Special Handling Instructions and Additional Information d) WMDS # 142772. Aerosol cans. In case of accident, contact Chemtrec at 800-424-9300. Weights are approximate. Load # 65400 DOT ERG #'s a)26 b)45 c)32 d)22 Apt time 6/6/91 0930							
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and Arkansas state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.							
Printed/Typed Name Robert G. Tuell, Jr.				Signature Robert G. Tuell, Jr. Month Day Year 060391			
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name Tony Figueroa				Signature Tony Figueroa Month Day Year 060391			
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name				Signature Month Day Year			
19. Discrepancy Indication Space							
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name KATHLEEN MOORE							
Signature Kathleen Moore Month Day Year 060691							

EPA Form 8700-22 (Rev. 9-88) Previous edition is obsolete.

NOTICE: THE ORIGINAL AND NOT LESS THAN TWO (2) COPIES MUST MOVE WITH THE HAZARDOUS WASTE SHIPMENT. ONCE DELIVERED, THE TREATMENT/STORAGE/DISPOSAL FACILITY MUST RETURN THIS ORIGINAL COPY TO THE GENERATOR.

BOE-C6-0222686

GENERAL INFORMATION

The Hazardous Waste manifest is designed to track waste from the point of generation to final disposal (cradle to grave). In order to accomplish this goal, it is essential that all items on the manifest be completed correctly. Incomplete or incorrect manifests are violations of the law, and could make you subject to civil or criminal liabilities as specified in the Federal Regulations and the Arkansas Hazardous Waste Management Code.

INSTRUCTIONS—IMPORTANT: READ ALL INSTRUCTIONS BEFORE COMPLETING

State and Federal regulations require Generators, Transporters, and Treatment, Storage & Disposal Facilities (TSDFs) to use this form and if necessary the continuation sheet for both inter and intrastate shipments. (Continuation sheets are not provided by the state of Arkansas.)

The Arkansas Manifest contains 6 copies. **ALL COPIES MUST BE LEGIBLE.** This form is designed for use on a 12 pitch (elite) typewriter; a firm ball point pen may also be used only if you press down HARD. The 6 copies must be distributed in the following way:

- ORIGINAL: GENERATOR COPY**—The TSDF will mail back to the generator state where the waste was generated. (WHITE COPY)
- COPY 2: STATE COPY**—The in-state TSDF mails to Arkansas Department of Pollution Control. (YELLOW COPY)
- COPY 3: TSDF COPY**—TSDF keeps this copy for his records. (PINK COPY)
- COPY 4: 2ND TRANSPORTER COPY**—The second transporter keeps for his records. (GOLD COPY)
- COPY 5: 1ST TRANSPORTER COPY**—The first transporter keeps for his records. (GREEN COPY)
- COPY 6: GENERATOR INITIAL COPY**—The generator keeps once first transporter signs off and takes waste. (BLUE COPY)

IF THE TSDF IS LOCATED OUT OF STATE THE IN-STATE GENERATOR MUST SEND A PHOTOCOPY TO THE ARKANSAS DEPARTMENT OF POLLUTION CONTROL ONCE THE MANIFEST HAS BEEN SIGNED OFF BY THE TSDF.

MANIFEST FORM ACQUISITION

1. If the destination (consignment) state supplies a manifest and requires its use, then the generator is obligated to obtain the manifest from that state.
2. If the destination state does not supply the manifest, but the generator state does, then the generator is obligated to obtain the manifest form from the generator state.
3. If forms are unavailable from either state the generator may obtain a manifest from any source.

ARKANSAS WILL NOT ACCEPT THE GENERIC UNIFORM MANIFEST

GENERATOR SECTION

- Item 1: **GENERATOR'S US EPA ID NO.—MANIFEST DOCUMENT NO.**—Enter the generator's 12-digit EPA identification number. The manifest document number is a unique 5-digit no. the generator assigns to each manifest.
- Item 2: **PAGE 1 Of** — Enter the total number of pages used to complete this manifest; i.e., the first page plus the number of continuation sheets, if any.
- Item 3: **GENERATOR'S NAME & MAILING ADDRESS**—Enter the name and mailing address of the generator, and provide the site address.
- Item 4: **GENERATOR'S PHONE NUMBER**—Enter a telephone no. with area code where an authorized agent of the generator can be reached in case of an emergency.
- Item 5: **TRANSPORTER 1 COMPANY NAME**—Enter the company name (as notified to EPA) of the first transporter who will transport the waste.
- Item 6: **US EPA ID NUMBER**—Enter the US EPA 12-digit ID number of the first transporter identified in Item 5.
- Item 7: **TRANSPORTER 2 COMPANY NAME**—If applicable, enter the company name (as notified to EPA) of the second transporter who will transport the waste. If more than (2) transporters will be used, use a continuation sheet and list the transporters in the order they will be transporting the waste.
- Item 8: **US EPA ID NUMBER**—If applicable, enter the US EPA 12-digit ID number of the second transporter identified in Item 7.
- Item 9: **DESIGNATED FACILITY NAME & SITE ADDRESS**—Enter the company name and site address of the treatment, storage, disposal facility (TSDF) designated to receive the waste listed on this manifest.
- Item 10: **US EPA ID NUMBER**—Enter the 12-digit US EPA identification number of the designated TSDF listed in Item 9.
- Item 11: **US DOT DESCRIPTION**—All of the following must be entered: the correct US DOT (Dept. of Transportation) name for the waste identified, the assigned DOT Hazard Class and the UN/NA ID Number (e.g. waste sulfuric acid, spent corrosive material, UN1832-RO). The word "waste" must appear as part of the DOT name. If more than 4 wastes are being shipped, a second manifest or continuation sheets must be used. (See 49 CFR 172.201)
- Item 12: **CONTAINERS (NO. & TYPE)**—Enter the number of containers for each waste and the appropriate abbreviations from Table 1, (below) for the type of containers used:

TABLE 1
CONTAINER TYPES

DM	-Metal drums, barrels, kegs
DW	-Wooden drums, barrels, kegs
DF	-Fiberboard or plastic drums, barrels, kegs
TP	-Tanks portable
TT	-Cargo tanks (tank trucks)
TC	-Tank cars
DT	-Dump truck
CY	-Cylinders
CM	-Metal boxes, cartons, cases (including roll-offs)
CW	-Wooden boxes, cartons, cases
CF	-Fiber or plastic boxes, cartons, cases
BA	-Burlap, cloth, paper or plastic bags

Item 13: **TOTAL QUANTITY**—Enter the total quantity of waste described on each line.

DO NOT USE FRACTIONS

Item 14: **UNIT (Wt./Vol.)**—Enter the appropriate abbreviation from Table 2 (below) for the unit of measure used in determining the total quantity of waste described on each line.

TABLE 2
UNITS OF MEASURE

G	-Gallons (liquid only)
P	-Pounds
T	-Tons (2,000 lbs.)
Y	-Cubic yards
L	-Liters (liquids only)
K	-Kilograms
M	-Metric Tons (1,000 kg)
N	-Cubic meters

Item 15: **SPECIAL HANDLING INSTRUCTIONS & ADDITIONAL INFORMATION**—Use this space to indicate special transportation, treatment, storage, disposal, or Bill of Lading information. If any alternate facility is designated, note it here. For INTERNATIONAL SHIPMENTS, generators must enter the point of departure (city & state) in this space.

Item 16: **GENERATOR'S CERTIFICATION**—The Generator must read, sign, (by hand), and date the certification. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water, air) inserted in the space. If another mode in addition to the highway mode is used, enter the appropriate additional mode in the space.

Item A: **STATE MANIFEST DOCUMENT NUMBER**—Number preprinted by the state of Arkansas except on the continuation sheets. Enter this number on each continuation sheet attached to the manifest.

Item B: **STATE GENERATOR ID**—Are numbers issued by state of Arkansas (i.e., PCB, Provisional, or Conditionally Exempt Generator Numbers).

Item C: **STATE TRAN #1 ID**—Must have Arkansas Permit Number if transporting waste in, through, or out of Arkansas.

Item D: **TRANSPORTER PHONE**—Enter a telephone number with area code where an authorized agent of the transporter can be reached.

Item E: **STATE TRAN #2 ID**—If applicable, enter Arkansas Permit Number if carrying waste in, through, or out of the Arkansas.

Item F: **TRANSPORTER PHONE**—If applicable, enter a telephone number with area code where an authorized agent of the second transporter may be reached.

Item G: **STATE FACILITY'S ID**—No entry is required by Arkansas.

Item H: **FACILITY PHONE**—Enter a telephone number with area code of the TSDF designated to receive the waste listed on the manifest.

Item I: **WASTE NO.**—Enter the 4-digit EPA Hazardous Waste No. as listed in 40 Code of Federal Regulations Part 261.

Item J: **ADDITIONAL DESCRIPTIONS FOR MATERIALS LISTED BELOW**—List additional description of material and alternate TSDF including TSDF address and EPA ID Number.

Item K: **EMERGENCY RESPONSE INFORMATION**—Arkansas requires the generator to list an authorized representative name and 24 hour phone number in case of an emergency.

TRANSPORTER SECTION

Item 17: **TRANSPORTER 1 ACKNOWLEDGEMENT**—Print or type the name of the person accepting the waste on behalf of the first transporter. That person must acknowledge acceptance of the waste described on the manifest by signing and entering the date of receipt.

Item 18: **TRANSPORTER 2 ACKNOWLEDGEMENT**—If applicable, follow instructions for item 17 for the second transporter.

Note: **ALL HAZARDOUS WASTE TRANSPORTERS OPERATING IN ARKANSAS MUST HAVE A VALID ARKANSAS TRANSPORTER PERMIT.**

DESIGNATED FACILITY (TSDF) SECTION

Item 19: **DISCREPANCY INDICATION SPACE**—The authorized representative of the designated facility must note in this space any significant discrepancy between the waste described on the manifest and the waste actually received at the facility. Any rejected materials should be listed here, along with an explanation of the disposition of the rejected wastes.

Item 20: **FACILITY OWNER/OPERATOR CERTIFICATION**—Print or type the name of the person accepting the waste on behalf of the owner/operator of the designated TSDF. That person must acknowledge acceptance of the waste described on the manifest by signing and entering the date.

Note: For interstate shipments you may be required to comply with the manifesting requirements of both the receiving and generator states regarding the completion of specific information included in lettered items A-K. Please check with both generator and disposer states for specific requirements.

BURDEN DISCLOSURE STATEMENT

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W., Washington, D.C. 20460; and to the Office of Information and Regulatory Affairs, Office Of Management and Budget, Washington, D.C., 20503.

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator's US EPA ID No. CAD086510005	Manifest Document No. 91080		22. Page 2 of 2	Information in the shaded areas is not required by Federal law.	
23. Generator's Name Douglas Aircraft Company					L. State Manifest Document Number AR509676		
24. Transporter Company Name <i>United Pumping</i>					M. State Generator's ID HAHQ36005698		
25. US EPA ID Number <i>CAD072933771</i>					N. State Transporter's ID		
26. Transporter Company Name					O. Transporter's Phone		
27. US EPA ID Number					P. State Transporter's ID		
					Q. Transporter's Phone		
28. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)					29. Containers	30. Total Quantity	31. Unit Wt/Vol
					No.	Type	R. Waste No.
a.	RQ, Waste, Kerosene Combustible Liquid, UN1223 (D001)				1	DM	200 P D001
b.	RQ, Waste, Flammable Liquid, N.O.S. (Standard Solvent) Flammable Liquid, UN1993 (D001)				1	DM	500 P D001
c.	RQ, Waste, Paint Related Material Combustible Liquid, NA1263 (F002, F003, F005)				4	DM	2000 P F002, F003, F005 U220, U229, U259 U220, U161
d.							
e.							
f.							
g.							
h.							
i.							
S. Additional Descriptions for Materials Listed Above					T. Handling Codes for Wastes Listed Above		
a) WMS # 146151, Kerosene.					A. 177+		
b) WMS # 156469, Standard Solvent.					B. 329+		
c) WMS # 146135, Paint Sludge.					C. 1924+		
32. Special Handling Instructions and Additional Information DOT ERG # a) 27. Weight is approximate. b) 27 c) 26							
33. Transporter <input checked="" type="checkbox"/> Acknowledgement of Receipt of Materials					Date		
Printed/Typed Name <i>MELVIN FARI'S</i>					Signature <i>Melvin Fari's</i>		Month Day Year 06/03/91
34. Transporter <input type="checkbox"/> Acknowledgement of Receipt of Materials					Date		
Printed/Typed Name					Signature		Month Day Year
35. Discrepancy Indication Space							



STATE OF ARKANSAS
Department of Pollution Control and Ecology
P. O. Box 8913 Little Rock, Arkansas 72219-8913
Telephone 501-562-7444

6

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-91


UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No.		2. Page 1 of 2		Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address Douglas Aircraft Company Attn: R. Tuell M/S C6-59 19503 S. Normandie Avenue, Torrance, CA 90502		C A D 0 8 6 5 1 0 0 0 5 9 1 0 8 0				A. State Manifest Document Number AR- 509676			
4. Generator's Phone (213) 533-7926 or 213-533-7231		5. Transporter 1 Company Name United Pumping Services		US EPA ID Number C A D 0 7 2 0 5 2 7 7 1		B. State Generator's ID HA035005408		C. State Transporter's ID PC 1123 H02	
7. Transporter 2 Company Name		8. US EPA ID Number				D. Transporter's Phone 818-961-9326		E. State Transporter's ID PC - - - - H - - -	
9. Designated Facility Name and Site Address Ensco, Inc. American Oil Road El Dorado, AR 71730		10. US EPA ID Number A R D 0 6 9 7 4 8 1 9 2				F. Transporter's Phone		G. State Facility's ID	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers		13. Total Quantity		14. Unit Wt/Vol		15. Waste No.	
a. RQ, Waste, Paint Related Material Flammable Liquid, NA1263 (F002,F003,F005)		0410 DM		2100010		P		F002,F003,F005 U080,U226,U239 U220,U161	
b. RQ, Waste, Oxidizer, Corrosive Solid, N.O.S. Oxidizer, NA9194 (D001,D002)(Potassium Nitrate)		0178 D		07181010		P		D001,D002	
c. RQ, Waste, Flammable Solid, N.O.S. (Dry Toner) Flammable Solid, UN1325 (D001)		0011 D		00091010		P		D001	
d. RQ, Waste, Compressed Gas, N.O.S. (Petroleum Distillates) Flammable Gas, UN1954 (D001)		0104 D		00081010		P		D001,U159 U220,U239	
J. Additional Descriptions for Materials Listed Above a)WMDS # 146135. Paint sludge. b)WMDS # 146142. Kerosene. c)WMDS # 142766. Dry toner. If no alternate TSDF, return to generator		K. Handling Codes for Wastes Listed Above EMERGENCY RESPONSE INFORMATION: 213-533-7926 Rob Tuell 213-830-1781 Tracy Takahashi							
15. Special Handling Instructions and Additional Information d)WMDS # 142772. Aerosol cans. In case of accident, contact Chemtrec at 800-424-9300. Weights are approximate. Load #65460 DOT ERG #'s a)26 b)45 c)32 d)22 Aqpt time 6/6/91 0930									
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and Arkansas state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.									
Printed/Typed Name Robert G. Tuell, Jr.		Signature <i>Robert G. Tuell, Jr.</i>				Month Day Year 10/6/91 3/9/11			
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name Tracy Takahashi		Signature <i>Tracy Takahashi</i>				Month Day Year 10/6/91 11/11			
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature				Month Day Year			
19. Discrepancy Indication Space									
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name		Signature				Month Day Year			

EPA Form 8700-22 (Rev. 9-88) Previous edition is obsolete.

GENERATOR INITIAL COPY

BOE-C6-0222689

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator's US EPA ID No. CAD086510005	Manifest Document No. 91080		22. Page 2 of 2	Information in the shaded areas is not required by Federal law.	
23. Generator's Name Douglas Aircraft Company					L. State Manifest Document Number AR509676		
					M. State Generator's ID NAHQ36005698		
24. Transporter Company Name			25. US EPA ID Number		N. State Transporter's ID		
26. Transporter Company Name			27. US EPA ID Number		O. Transporter's Phone		
					P. State Transporter's ID		
					Q. Transporter's Phone		
28. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)					29. Containers	30. Total Quantity	31. Unit Wt/Vol
					No.	Type	R. Waste No.
a.	RQ, Waste, Kerosene Combustible Liquid, UN1223 (D001)				1	DM	200 P D001
b.	RQ, Waste, Flammable Liquid, N.O.S. (Standard Solvent) Flammable Liquid, UN1993 (D001)				1	DM	500 P D001
c.	RQ, Waste, Paint Related Material Combustible Liquid, NA1263 (F002, F003, F004)				4	DM	2000 P F002, F003, F004, U000, U226, U239, U220, U161
d.							
e.							
f.							
g.							
h.							
i.							
S. Additional Descriptions for Materials Listed Above					T. Handling Codes for Wastes Listed Above		
a) UN1223 # 146151, Kerosene. b) UN1993 # 156469, Standard Solvent. c) UN1263 # 146185, Paint Sludge.							
32. Special Handling Instructions and Additional Information DOT ERG # a) 27. Weight is approximate. b) 27 c) 26							
33. Transporter Acknowledgement of Receipt of Materials					Date		
Printed/Typed Name				Signature		Month Day Year	
34. Transporter Acknowledgement of Receipt of Materials					Date		
Printed/Typed Name				Signature		Month Day Year	
35. Discrepancy Indication Space							



LAND DISPOSAL RESTRICTION NOTIFICATION FORM

SECTION I

Generator Name: Douglas Aircraft Co
Address: 19503 S. Normandie Ave
Torrance, CA 90502
USEPA ID No.: CA0086570005

Manifest No.: AR509676

WMDS No.(s): 146135, 146142, 142768, 142772, 146151

Completed By: X

Title: X

Date: X

(Continuation Sheets may be attached and are numbered accordingly: Page 1 of 2)

SECTION II SPENT SOLVENT WASTE (268.30) AND CALIFORNIA LIST WASTE (268.32)

(Check Here) ☒

A. Spent Solvent Wastes

The shipment, as referenced by the above manifest number, contains waste(s) which correspond to USEPA Hazardous Waste Code(s) F002, F003, F005

The above referenced waste(s) must be treated to meet the treatment standard expressed as Constituent Concentration in the Waste Extract as outlined in 40 CFR 268.41 Table CCWE below.

Table CCWE—Constituent Concentrations in Waste Extract

F001-F005 Spent Solvents	Concentration (in mg/l)	
	Wastewaters containing spent solvents	All Other spent solvent wastes
Acetone	0.05	0.50
n-Butyl alcohol	5.0	5.0
Carbon disulfide	1.05	4.81
Carbon tetrachloride	.05	.96
Chlorobenzene	.15	.05
Cresols (and cresylic acid)	2.82	.75
Cyclohexanone	.125	.75
1,2-Dichlorobenzene	.65	.125
Ethyl acetate	.05	.75
Ethylbenzene	.05	.053
Ethyl ether	.05	.75
Isobutanol	5.0	5.0
Methanol	.25	.75
Methylene chloride	.20	.96
Methylene chloride (from the pharmaceutical industry)	12.7	.96
Methyl ethyl ketone	0.05	0.75
Methyl isobutyl ketone	0.05	0.33
Nitrobenzene	0.66	0.125
Pyridine	1.12	0.33
Tetrachloroethylene	0.079	0.05
Toluene	1.12	0.33
1,1,1-Trichloroethane	1.05	0.41
1,1,2-Trichloro-1,2,2-Trifluoroethane	1.05	0.96
Trichloroethylene	0.062	0.091
Trichlorofluoromethane	0.05	0.96
Xylene	0.05	0.15

☐ —If indicated by "X," any or all of the above specified waste codes are referenced to Certification Statement Section VI.

"X" here, if applicable

K-78

(Check Here) ☐

B. California List Wastes

This shipment, as referenced by the above manifest number, contains waste(s) corresponding to USEPA Hazardous Waste Code(s) _____

The above referenced waste(s) must be treated to meet the treatment standards as set forth in 40 CFR 268 Subpart D, or where specific treatment standards are not applicable, the waste must be treated in accordance with the requirements specified in 40 CFR 268.32 and RCRA Section 3004(d).

CALIFORNIA LIST CONSTITUENTS AND THEIR PROHIBITION LEVELS

CONSTITUENT	CONCENTRATION (MG/L)
Cyanides	1,000
Arsenic	500
Cadmium	100
Chromium VI	500
Lead	500
Mercury	20
Nickel	134
Selenium	100
Thallium	130
Liquids with pH \leq 2.0	—
Hazardous Waste Liquids with PCBs	50 ppm
Wastes containing HOCs*	1,000 mg/kg

* Halogenated Organic Carbon (See 40 CFR Appendix III).

☐ —If indicated by "X," any or all of the above specified waste codes are referenced to certification statement Section VI.
"X" here, if applicable

SECTION III

OTHER RESTRICTED WASTES

Restricted Waste(s) contained in this shipment and referenced by the above manifest no. are listed below and are subject to the treatment standards set forth in 268.41, 268.42, and/or 268.43.

For each waste code, list the following information: Subcategory, if applicable; Treatability Group (NWW or WW); 5-letter treatment code for specified technology in 268.42, if applicable (INCIN, DEACT, STABL) or CFR Section and Paragraph for Concentration based standards, if applicable (268.41(a) and/or 268.43(a)).

USEPA Hazardous Waste Code(s)	Subcategory If Applicable	Treatability Group	Treatment Technology (5-letter treatment Code 268.42(a))	CFR Section and Paragraph (268.41(a) and/or 268.43(a))	Waste Codes Indicated By "X" are Referenced to Certification Statement Section VI
U080		NWW		268.43(a)	
U22C		NWW		268.43(a)	
U239		NWW		268.43(a)	
U220		NWW		268.43(a)	
U161		NWW		268.43(a)	
D001	Ignitable Liquid	NWW	INCIN		
D002	Alkaline Solid	NWW	DEACT		
U159		NWW		268.43(a)	
R1	Ignitable Solid	NWW	INCIN		

D001 Ignitable Gases
D001 Oxidizer



ensco
environmental systems company

SECTION IV**LAB PACK CERTIFICATION**

In accordance with 40 CFR 268.7(a)(7) and (8) and regarding those lab pack wastes corresponding to USEPA Hazardous Waste Code(s) _____

identified as restricted wastes contained in this shipment and referenced by the above manifest no., I submit the following certification statement(s) where applicable:

**Appendix IV Lab Pack Wastes
(Organometallic)**

I certify under penalty of law that I personally have examined and am familiar with the waste and that the lab pack contains only the wastes specified in Appendix IV to part 268 or solid wastes not subject to regulation under 40 CFR Part 261. I am aware that there are significant penalties for submitting a false certification, including the possibility of fine or imprisonment.

Signature _____

Title _____ Date _____

Lab Pack Wastes with hazardous waste codes not specified by EPA in Appendix IV or V are referenced in Section III of this form.

**Appendix V Lab Pack Wastes
(Organic)**

I certify under penalty of law that I personally have examined and am familiar with the waste through analysis and testing or through knowledge of the waste and that the lab pack contains only organic wastes specified in Appendix V to Part 268 or solid wastes not subject to regulation under 40 CFR Part 261. I am aware that there are significant penalties for submitting a false certification, including the possibility of fine or imprisonment.

Signature _____

Title _____ Date _____

SECTION V**RESTRICTED WASTE SUBJECT TO AN EXTENSION IN THE EFFECTIVE DATE
(40 CFR 268 Appendix VII & VIII)**

The wastes contained in this shipment as referenced by the above manifest no. which are subject to an Extension in the Effective Date in accordance with 40 CFR Subpart C are identified below:

USEPA Hazardous Waste Code/
Treatability Group (NWW or WW)

Extension Date

(These wastes may be subject to the California List Prohibitions)

SECTION VI**CERTIFICATION OF RESTRICTED WASTE WHICH MAY BE LAND DISPOSED
WITHOUT FURTHER TREATMENT**

In accordance with 268.7(a)(2) and regarding those restricted waste(s) contained in this shipment, these waste(s) may be land disposed without further treatment. I submit the following certification statement:

I certify under penalty of law that I personally have examined and am familiar with the waste through analysis and testing or through knowledge of the waste to support this certification that the waste complies with the treatment standards specified in 40 CFR Part 268 Subpart D and all applicable prohibitions set forth in 40 CFR 268.32 or RCRA section 3004(d). I believe that the information I submitted is true, accurate and complete. I am aware that there are significant penalties for submitting a false certification, including the possibility of a fine and imprisonment.

Signature _____ Title _____ Date _____

(This certification is referenced to the appropriate USEPA Hazardous Code(s) in the foregoing appropriate Sections II or III).

Waste analysis is attached where available, otherwise, the information contained herein is based upon my thorough knowledge of the waste(s).

I hereby certify that all information submitted in this document is complete and accurate to the best of my knowledge and information:

Signature X Title X Date X

GKH 7/90





UNITED PUMPING SERVICE, INC.

FIELD WORK ORDER

19916

14016 EAST VALLEY BOULEVARD
CITY OF INDUSTRY, CALIFORNIA 91746
PHONE: (818) 961-9326
FAX (818) 336-7734

PAGE 1 OF 1

CUSTOMER/ADDRESS	
Douglas AIRCRAFT	
19503 S. NORMANDIE AVE	
Torrance CA 90502	
PHONE NO.	CONTACT: TRACY
LOCATION:	Bldg #45

DATE WORK PERFORMED:
6-3-91
DATE OF THIS REPORT:
TIME CALL RECEIVED:
CONTRACT NO.:
LOSS REPORT NO./P.O. NO.:

SCOPE OF WORK:
Picked up Load of Drums
FOR ENSCO AR.

EQUIPMENT: TYPE	EQUIPMENT NO.	OPERATOR NAME	START TIME	ARRIVE TIME	TIME OUT	STOP TIME	S.T. TIME	O.T. TIME	TOTAL HOURS
TRUCK VAN 3	26	Tony F.	0530	0710	0945				

PERSONNEL: NAME	TITLE	START TIME	ARRIVE TIME	TIME OUT	STOP TIME	S.T. TIME	O.T. TIME	TOTAL HOURS

DISPOSAL: MANIFEST NO.	DISPOSAL SITE	QTY	UNIT
AR-509676	ENSCO	129	DM

CONSUMABLE: TYPE	QTY	TYPE	QTY

ADDITIONAL INFORMATION:

SIGNED:

X Tony Takahashi - IT Corp



UNITED PUMPING SERVICE, INC. FIELD WORK ORDER

19916

14016 EAST VALLEY BOULEVARD
CITY OF INDUSTRY, CALIFORNIA 91746
PHONE: (818) 961-9326
FAX (818) 336-7734

PAGE 1 OF 1

CUSTOMER/ADDRESS: Douglas Aircraft
19503 S. Normandie Ave
TORRANCE CA 90502
PHONE NO: CONTACT: TRACY
LOCATION: Bldg # 45

DATE WORK PERFORMED: 6-3-91
DATE OF THIS REPORT:
TIME CALL RECEIVED:
CONTRACT NO.:
LOSS REPORT NO./P.O. NO.:

SCOPE OF WORK: Picked up Load of Drums
FOR ENSCO AR.

EQUIPMENT: TYPE	EQUIPMENT NO.	OPERATOR NAME	START TIME	ARRIVE TIME	TIME OUT	STOP TIME	S.T. TIME	O.T. TIME	TOTAL HOURS
TRUCK VAN 3	26	Tony F.	0530	0710	0945				

PERSONNEL NAME	TITLE	START TIME	ARRIVE TIME	TIME OUT	STOP TIME	S.T. TIME	O.T. TIME	TOTAL HOURS

DISPOSAL: MANIFEST NO.	DISPOSAL SITE	QTY	UNIT
AR-509676	ENSCO	129	DM

CONSUMABLE: TYPE	QTY	TYPE	QTY

ADDITIONAL INFORMATION:

SIGNED

X Tony Takahashi - IT Corp

REQUEST FOR
FACILITIES MATERIAL

Serial No.

175235

☐ EMERGENCY (JUSTIFICATION)☐ CRITICAL☐ ROUTINE

Requested By Rob Tuell	Employee No. C330487	Phone 533-7926	Date 07-03-91	Dept C6-722	Bldg & Column 45	Benefiting Dept C6-722
Acct. No./CCN	PEMO/Source	Maint Work Order/ARO			Date Material Required Job is complete.	

Item	Qty	O/U	Vendor Part No.	Description/Manufacturer
				This 70-90 is being written to follow up on Transportation and disposal of drums of hazardous waste at Enco, Inc. in El Dorado, Arkansas. The waste was transported by United Pumping Service, Inc. on June 03, 1991.
				United Work Order No. 19916
				Manifest No. AR-509676
				The work is complete

JUSTIFICATION

This work was required to comply with Hazardous Waste Regulations.

Suggested Supplier

United Pumping Service

SUBTOTAL

TAX

TOTAL

Phone No.

(818) 961-9326

MATERIAL FOR

AUTHORIZED SIGNATURES

Machine/Equipment

Signature

Date

Rob Tuell**07-03-91**

Model/Manufacture

Stockroom Coord

Date

Serial No.

Section Mgr.

Date

Deliver To

Size/Type

Branch Mgr.

Date

Bldg.

Column

Dept.

DAC/Control Number

Bldg/Column

Acquisition Sec. Mgr.

Date

Name

Ext.

☐ DISTRIBUTION

G

AM

PM

Assigned To

Reassigned To

PLANT SERVICES ACQUISITION ONLY

ANALYST

Supplier	Work Order No.	Name	Date
Supplier Name/Address	Purchase/Contract No.	Expected Shipment Date	
CCN	Ship to Location		
Supplier Contact	City to Ship	PEMO/Source	FOB

DISTRIBUTION: White, Canary and Blue - Plant Services Acquisitions; Pink - Originator

Estimated Total Cost: \$35,000.00